

# Home Report

One triangle, all angles covered

RESIDENTIAL / COMMERCIAL / PROPERTY & CONSTRUCTION



# Contents

- 1. Single Survey
- 2. Energy Performance Certificate







# Scottish Single Survey



### survey report on:

Property address	20 Mona Crescent Broughty Ferry Dundee DD5 3FB
Customer	Clare Lyall
Customer address	20 Mona Crescent Broughty Ferry Dundee DD5 3FB
Prepared by	Shepherd Chartered Surveyors
Date of inspection	11/04/2024



www.shepherd.co.uk

#### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by marking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller:
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
  or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report<sup>2</sup>.

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;

- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments

being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use

communal grounds, parking areas, and other facilities;

- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a detached two storey house built by Kirkwood Homes to the "Craig" specification.	
Accommodation	GROUND FLOOR: Entrance Hallway, Lounge, Open Plan Dining Kitchen and Family Room, Utility Room, Fourth Bedroom and Separate WC Compartment.  FIRST FLOOR: Master Bedroom with En Suite Bathroom,	
	Two additional Bedrooms and Bathroom.	
Gross internal floor area (m²)	136 sq metres approximately.	
Neighbourhood and location	The property forms part of a modern private residential development currently under construction and located at the northern most point of Broughty Ferry, where a wide range of local amenities and facilities can be found in close proximity.	
Age	Built circa 2020 and subsequently altered with the conversion of the garage in 2023.	
Weather	Dry and bright.	
Chimney stacks	None.	

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof over the main dwelling is of pitched timber construction, overlaid in a plyboard style sarking and externally clad in concrete tiles, which incorporates tiled detailing at the ridge line with PVC caps at the verge. Dormer projections form part of the roof design which are of timber frame construction clad in hanging tile and timber weatherboarding panelling, while the roof coverings are of pitched timber and tiled design.
	Full and safe access was not available to the roof void area due to the presence of a thick layer of insulation throughout and the absence of flooring or crawl boards.
Rainwater fittings	Visually inspected with the aid of binoculars where
	appropriate.
	PVC gutters and downpipes.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of load bearing timber frame construction with a masonry outer leaf finished in wet dash.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows are of uPVC double glazed design, while access at the front and rear elevation is via composite style double glazed entrance doors. There are PVC double glazed French doors from the open plan kitchen which lead out to the garden patio.
	Painted timber eaves and soffit boarding to the external fabric.
External decorations	Visually inspected.
	Low maintenance PVC finishes and painted external joinery.
Conservatories / porches	None.
Communal areas	None apparent.
Garages and permanent outbuildings	Visually inspected.
Garages and permanent outbuildings	Visually inspected.  The former garage has now been converted into habitable accommodation.
Garages and permanent outbuildings	The former garage has now been converted into habitable
Garages and permanent outbuildings  Outside areas and boundaries	The former garage has now been converted into habitable accommodation.  Remaining outbuildings comprise a garden shed of timber and felt construction.
	The former garage has now been converted into habitable accommodation.  Remaining outbuildings comprise a garden shed of timber
	The former garage has now been converted into habitable accommodation.  Remaining outbuildings comprise a garden shed of timber and felt construction.  Visually inspected.  The full extent of the site should be outlined and confirmed
	The former garage has now been converted into habitable accommodation.  Remaining outbuildings comprise a garden shed of timber and felt construction.  Visually inspected.  The full extent of the site should be outlined and confirmed with the Title Deeds.  Garden grounds to the front are laid in grass, while the rear garden has been landscaped and set out with a feature paved patio space and the remaining area is laid in artificial grass and boundaries where determined are made up of timber fencing. A private monoblock driveway provides off

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal partitions where tested are of timber stud construction overlaid in plasterboard with painted and decorated finishes.
Floors including sub floors	Solid concrete construction at ground floor level and suspended timber at first. Due to fitted carpets and floor coverings no detailed inspection was possible of the floors and accordingly no comment can be made on their condition.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Kitchen units comprise modern wall and base mounted fixtures and fittings with additional facilities available via the separate utility room.
	Internal doors are of timber construction with painted skirtings and facings throughout.
Chimney breasts and fireplaces	None.
Internal decorations	Visually inspected.
	Painted and decorated finishes.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  Mains supply of electricity with the electrical consumer unit and meter located in the under stair storage cupboard.  There are photovoltaic roof panels inset within the roof design, presumed to be connected to a feed-in tariff and all details should be confirmed.

#### Gas

Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.

Mains supply of gas.

#### Water, plumbing, bathroom fittings

Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.

No tests whatsoever were carried out to the system or appliances.

Mains supply of water with the plumbing where seen being of PVC and copper type.

Sanitary fittings are on modern lines and comprise a two piece WC compartment at ground floor level and a three piece main bathroom suite at first floor, while the master bedroom benefits from a four piece en-suite bathroom with a separate shower cubicle.

#### Heating and hot water

Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.

No tests whatsoever were carried out to the system or appliances.

Gas fired central heating and hot water system via the 'Baxi Assure' boiler which is located and boxed in within the fourth bedroom (former garage). Radiators in the main apartments with individual thermostatic control valves, while in the bathroom and en-suite there are wall mounted towel rails.

#### Drainage

Drainage covers etc. were not lifted.

Neither drains nor drainage systems were tested.

All foul and surface water drainage is presumed to be connected to the main public sewer. The system was not tested.

#### Fire, smoke and burglar alarms

#### Visually inspected.

No tests whatsoever were carried out to the system or appliances.

All Scottish homes require a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbonfuelled appliance such as a boiler, open fire or wood burner, a carbon monoxide detector is also required. We have not assessed or tested any existing equipment and it is the purchasers responsibility to confirm that the property will comply with these standards following a change of ownership.

#### Any additional limits to inspection

The property was fully furnished and had fitted floor coverings, therefore no detailed inspection was possible of the floors and accordingly, no comment can be made on their condition. Internal cupboards were generally filled with storage items. No access was available beneath sanitary or kitchen fittings.

Windows and external doors were not all fully opened or tested.

Full and safe access was not available to the roof void area due to the presence of a thick layer of insulation throughout and the absence of flooring or crawl boards.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.

#### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- (3) Chimney head
- (4) Flashing
- 5) Ridge ventilation
- (6) Ridge board
- (7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10) Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- 13) Roof felt
- (14) Trusses
- (15) Collar
- 16) Insulation
- (17) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- (24) Chimney breast
- 25) Window pointing
- 26) Window sills
- 27) Rendering
- 28) Brickwork / pointing
- 29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- (33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40) Hot water tank

#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	•

Structural movemen	nt
Repair category	1
Notes	There was no evidence of significant structural movement within the limitations of our inspection.

Dampness, rot and infestation	
Repair category	1
Notes	Damp meter readings were taken where considered appropriate within the property and moisture levels were found to be within an acceptable range.

Chimney stacks	
Repair category	N/A
Notes	None.

Roofing including roof space	
Repair category	1
Notes	No significant defects were noted at the time of inspection. Roofing contractors recommend that roof coverings are inspected regularly in order to ensure they remain watertight.

Rainwater fittings	
Repair category	1
Notes	Within the limitations of our inspection rainwater goods were seen to be free from significant defect.  We would highlight that it was not raining at the time of our inspection and
	we would recommend that all rainwater fittings be inspected during heavy rainfall in order to ensure they are free from defect.

Main walls	
Repair category	1
Notes	Isolated areas of hairline cracking to the wet dash finishes, patch repair and repoint where required.  Within the limitations of our inspection, no significant defects were noted, however normal levels of maintenance are recommended.

Windows, external doors and joinery	
Repair category	1
Notes	Windows and doors were not all fully opened or tested, and it should be appreciated that some defects are only evident during certain weather conditions. Within the limitations of our inspection, no significant defects were noted.  Finishing works are required internally to the window frame within the
	converted ground floor bedroom (former garage).

External decorations	
Repair category	1
Notes	Paint finished and decorated external surfaces will require redecoration on a regular basis.

Conservatories/porches	
Repair category	N/A
Notes	None.

Communal areas	
Repair category	N/A
Notes	None.

Garages and permanent outbuildings	
Repair category	1
Notes	Normal maintenance will be required to the garden shed.

Outside areas and boundaries	
Repair category	1
Notes	Boundary areas and fences should be regularly checked and maintained as necessary.

Ceilings	
Repair category	1
Notes	Cosmetic plaster blemishes and shrinkage cracking consistent with a modern property. This should be attended to as part of routine redecoration.

Internal walls	
Repair category	1
Notes	Cosmetic plaster blemishes and shrinkage cracking consistent with a modern property. This should be attended to as part of routine redecoration.

Floors including sub-floors	
Repair category	1
Notes	Due to fitted carpets and floor coverings no detailed inspection of floors was possible and accordingly no comment can be made on their condition.

Internal joinery and kitchen fittings	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Chimney breasts and fireplaces	
Repair category	N/A
Notes	None.

Internal decorations	
Repair category	1
Notes	The property is in good decorative order.

Cellars	
Repair category	N/A
Notes	None

Electricity	
Repair category	1
Notes	The Institution of Engineering Technology recommends that inspections and testings are undertaken at least every five years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations.  There are photovoltaic roof panels inset within the roof design, presumed to
	be connected to a feed-in tariff and all details should be confirmed.

Gas	
Repair category	1
Notes	In the interests of safety and in light of recent regulations it would be prudent to have all gas appliances checked by a Gas Safe registered contractor.

Water, plumbing and bathroom fittings		
Repair category	1	
Notes	No tests have been undertaken of the system, however within the limitations of our inspection, no significant defects were noted. No inspection has been possible to enclosed timbers beneath wet appliances and no comment has been made on the condition of unseen areas. Watertight seals will require to be regularly checked and replaced, to prevent water damage to adjoining areas.  Spillage apparent around the shower cubicle within the en-suite bathroom. No access was available beneath sanitary fittings and a precautionary	
	check for damp/rot is recommended.	

Heating and hot water		
Repair category	1	
Notes	It is assumed that the central heating system has been properly installed, updated and maintained to meet with all current regulations and standards with particular regard to fluing and ventilation requirements. Service records should be obtained and checked. In the absence of service documentation further advice should be obtained from a qualified heating engineer to ascertain the condition and efficiency of the system.	

Drainage	
Repair category	1
Notes	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	N/A
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	N/A
Communal areas	N/A
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	N/A
Internal decorations	1
Cellars	N/A
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Wherea lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?		Ground & First Floor.		
2. Are there three steps or fewer to a main entrance door of the property?		X	No	
3. Is there a lift to the main entrance door of the property?	Yes		No	X
4. Are all door openings greater than 750mm?	Yes		No	X
5. Is there a toilet on the same level as the living room and kitchen?	Yes	X	No	
6. Is there a toilet on the same level as a bedroom?	Yes	X	No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes		No	X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes	X	No	

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The property was completed in 2020 by Kirkwood Homes, a builder registered under the NHBC scheme. The remainder of a building warranty will be available, all details should be confirmed.

The property has been altered with the conversion of the garage and it is presumed where required that all relevant Local Authority consents and documentation are available and in order and this should be confirmed.

The property forms part of a modern residential development and there may be a factoring charge for the upkeep and maintenance of common areas and all details and costings should be confirmed.

It is assumed that there are no statutory, town planning, road proposals or environmental matters which are likely to have an adverse effect on the property.

The road and footpath adjoining the site are made up and are assumed to be adopted by the Local Authority.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

#### Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £360,000 (THREE HUNDRED AND SIXTY THOUSAND POUNDS STERLING).

This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

#### Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £330,000 (THREE HUNDRED AND THIRTY THOUSAND POUNDS STERLING).

Signed	Barry Reid
	Electronically signed :- 15/04/2024 16:38

Report author	Barry Reid
Company name	J & E Shepherd Chartered Surveyors
Address	13 Albert Square Meadowside Dundee DD1 1XA
Date of report	11/04/2024



www.shepherd.co.uk

Property Address			
Address Seller's Name Date of Inspection	20 Mona Crescent, Broughty Ferry, Dundee, DD5 3FB Clare Lyall 11/04/2024		
Property Details			
Property Type X House Purpose built flat	Bungalow Purpose built maisonette Converted maisonette Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)		
Property Style X Detached Back to back	Semi detached       Mid terrace       End terrace         High rise block       Low rise block       Other (specify in General Remarks)		
Does the surveyor believe that the military, police? Flats/Maisonettes only Floor(s) on what Approximate Year of Construction	property was built for the public sector, e. g. local authority,  No. of floors in block  No. of units in block  2020  No. of units in block		
Tenure			
X Absolute Ownership	Other		
Accommodation			
Number of Rooms  2 Living room 2 Bathroom(s			
Gross Floor Area (excluding garage	es and outbuildings) 136 m² (Internal) m² (External)		
Residential Element (greater than 40%)			
Garage / Parking / Outbuildings			
Single garage Double gar	rage X Parking space No garage / garage space / parking space		
Available on site? X Yes	No		
Permanent outbuildings:			
No permanent outbuildings.			

Construction			
Walls Br Roof X Ti	rick Stone Concre		Other (specify in General Remarks)  Other (specify in General Remarks)
KOOI 🔼 III	eState Aspirati	reit	Other (speedly in Ocheral Nemarks)
Special Risks			
Has the property suffered	structural movement?		☐ Yes X No
If Yes, is this recent or pro			Yes No
·	or reason to anticipate subsi	dence, heave, landslip	or flood in Yes X No
If Yes to any of the above	, provide details in General R	emarks.	
Service Connections			
Based on visual inspection the supply in General Ren		to be non-mains, pleas	e comment on the type and locationof
Diamage	ains Private ains Private Private Private Partial	None Water None Gas None	X       Mains       Private       None         X       Mains       Private       None
	al Heating and any non mains	services:	
Gas fired central heating.			
0:1-			
Site  Apparent legal issues to b	ne verified by the conveyance	r Please provide a brie	of description in General Remarks.
	ared drives / access Garage or o	•	`
	ricultural land included with property		Other (specify in General Remarks)
Location			
X Residential suburb Commuter village	Residential within town / city Remote village	Mixed residential / com	mercial Shared service connections Other (specify in General Remarks)
Planning Issues			
Has the property been ext If Yes provide details in G	tended / converted / altered? eneral Remarks.	X Yes No	
Roads			
	nade road Partly completed r	new road Pedestrian acce	ess only Adopted Unadopted

#### **General Remarks**

The subjects comprise a detached two storey house built by Kirkwood Homes which forms part of a modern private residential development currently under construction and located at the northern most point of Broughty Ferry, where a wide range of local amenities and facilities can be found in close proximity.

At the time of inspection the property was found to be in a condition consistent with its age and type of construction.

OTHER ACCOMMODATION: Utility Room.

The property was completed in 2020 by Kirkwood Homes, a builder registered under the NHBC scheme. The remainder of a building warranty will be available, all details should be confirmed.

The property has been altered with the conversion of the garage and it is presumed where required that all relevant Local Authority consents and documentation are available and in order and this should be confirmed.

The property forms part of a modern residential development and there may be a factoring charge for the upkeep and maintenance of common areas and all details and costings should be confirmed.

Essential Repairs		
None.		
Estimated cost of essential repairs [		
Retention recommended?	Yes X No	
Retention amount		
Comment on Mortgageability		
The property forms suitable security for m	nortgage purposes subject to the specific lending criteria of any mortga	je provider.
Valuation		
Market value in present condition		£ 330,000
Market value on completion of ess	ential repairs	£
Insurance reinstatement value		£ 360,000
(to include the cost of total rebuilding,	site clearance, professional fees, ancillary charges plus VAT)	
Is a reinspection necessary?		Yes X No

#### Declaration

Signed Barry Reid

Electronically signed :- 15/04/2024 16:38

Surveyor's name Barry Reid Professional qualifications MRICS

Company name J & E Shepherd Chartered Surveyors

Address 13 Albert Square, Meadowside, Dundee, DD1 1XA

Telephone 01382 200454

Email Address dundeeresidential@shepherd.co.uk

Date of Inspection 11/04/2024



# **Energy Performance Certificate**



### **Energy Performance Certificate (EPC)**

**Dwellings** 

### **Scotland**

#### 20 MONA CRESCENT, BROUGHTY FERRY, DUNDEE, DD5 3FB

Dwelling type:Detached houseDate of assessment:11 April 2024Date of certificate:12 April 2024Total floor area:136 m²

Primary Energy Indicator: 109 kWh/m²/year

Reference number: 1314-5524-8530-2319-5292
Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst

**Main heating and fuel:** Boiler and radiators, mains

gas


#### You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

#### Estimated energy costs for your home for 3 years\*

£3,546

 $^st$  based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (82)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (82)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	****	****
Roof	Pitched, insulated (assumed) Roof room(s), insulated (assumed)	**** ****	**** ****
Floor	Solid, insulated (assumed)	_	_
Windows	Fully double glazed	****	****
Main heating	Boiler and radiators, mains gas	****	****
Main heating controls	Programmer, room thermostat and TRVs	****	****
Secondary heating	None	_	_
Hot water	From main system	****	****
Lighting	Low energy lighting in all fixed outlets	****	****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use,  $CO_2$  emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 19 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.6 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings	
Heating	£2,589 over 3 years £2,589 over 3 years			
Hot water	£477 over 3 years	£477 over 3 years	N. 4	
Lighting	£480 over 3 years	£480 over 3 years	Not applicable	
Totals	£3,546	£3,546		

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

None

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

#### LZC energy sources present:

Solar photovoltaics

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	8,349	N/A	N/A	N/A
Water heating (kWh per year)	1,850			

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:

Assessor membership number:

Company name/trading name:

Address:

Mr. Barry Reid

EES/016131

J & E Shepherd

12 Atholl Crescent

Edinburgh EH3 8HA 0131 225 123

Phone number: 0131 225 1234

Email address: edinburgh@shepherd.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.





Property address	20 Mona Crescent Broughty Ferry Dundee DD5 3FB
Seller(s)	Clare Lyall
Completion date of property questionnaire	14/04/2024

#### **Note for sellers**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

#### Information to be given to prospective buyer(s)

1.	Length of ownership		
	How long have you owned the proper	ty?	3 1/2 years
2.	Council tax		
	Which Council Tax band is your prope	erty in?	E
3.	Parking		
	What are the arrangements for parkin (Please tick all that apply)		
	Garage	No	
	Allocated parking space	No	
	• Driveway	Yes	
	Shared parking	No	
	On street	Yes	
	Resident permit	No	
	Metered Parking	No	
	Other (please specify):		
4.	Conservation area		
	Is your property in a designated Cons special architectural or historical inte which it is desirable to preserve or er	rest, the character or appea	ea of No rance of

_	Literation Williams			
5.	Listed buildings			
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	No		
6.	Alterations/additions/extensions			
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes		
	If you have answered yes, please describe below the changes which you have made:			
	Garage converted to additional room			
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes		
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.			
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:			
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	No		
	If you have answered yes, please answer the three questions below:			
	(i) Were the replacements the same shape and type as the ones you replaced?			
	(ii) Did this work involve any changes to the window or door openings?			
	(iii) Please describe the changes made to the windows doors, or patio doors approximate dates when the work was completed):	(with		
	Please give any guarantees which you received for this work to your solicito agent.	r or estate		
7.	Central heating			
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes		
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).			

	Gas			
	If you have answered yes, ple	ease answer the three q	uestions below:	
	i) When was your central hea installed?	ting system or partial c	entral heating system	
	3 1/2 years ago			
	(ii) Do you have a maintenand	ce contract for the cent	ral heating system?	No
	If you have answered yes, ple you have a maintenance con		company with which	
	(iii) When was your maintena (Please provide the month ar		ewed?	
8.	Energy Performance Certification	ate		
	Does your property have an than 10 years old?	Energy Performance Ce	ertificate which is less	Yes
9.	Issues that may have affected your property			
a.	Has there been any storm, flood, fire or other structural damage to the property while you have owned it?		No	
	If you have answered yes, is insurance claim?	the damage the subject	t of any outstanding	
b.	Are you aware of the existen	ce of asbestos in your բ	property?	No
	If you have answered yes, plo	ease give details:		
10.	Services			
a.	Please tick which services ar supplier:	e connected to your pro	operty and give details o	of the
	Services	Connected	Supplier	
	Gas or liquid petroleum gas	Yes	British Gas	
	Water mains or private water supply	Yes	Scottish Water	
	Electricity	Yes	Octopus Energy	/
	Mains drainage	Yes	Tayside	
	Telephone	Yes	ВТ	

	Cable TV or satellite	Yes	Sky	
	Broadband	Yes	ВТ	
b.	Is there a septic tank syste	m at your property?		No
	If you have answered yes,	please answer the tw	vo questions below:	
	(i) Do you have appropriate tank?	consents for the di	scharge from your septic	
	(ii) Do you have a maintena	ance contract for you	ur septic tank?	
	If have answered yes, detainmaintenance contract:	ils of the company w	vith which you have a	
11.	Responsibilities for shared	l or common areas		
a.	Are you aware of any respused jointly, such as the reboundary, or garden area	repair of a shared d	bute to the cost of anything rive, private road,	No
	If you have answered yes	, please give details	s:	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?			No
	If you have answered yes	, please give details	s:	
C.	Has there been any major r during the time you have o		t of any part of the roof	No
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?		No	
	If you have answered yes,	, please give details	::	
e.	As far as you are aware, d walk over your property, f maintain their boundaries	for example to put o		No
	If you have answered yes,	, please give details	::	
f.		ht of way is a way o	nt of way across any part of over which the public has a ately-owned.)	No
	If you have answered yes,			1

12.	Charges associated with the property	
a.	Is there a factor or property manager for your property?  If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	No
b.	Is there a common buildings insurance policy?  If you have answered yes, is the cost of the insurance included in monthly/annual factor's charges?	No
c.	Please give details of any other charges you have to pay on a regular ba upkeep of common areas or repair works, for example to a residents' as or maintenance or stair fund.  James Gibb property management	
13.	Specialist work	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?  If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	No
b.	As far as you are aware, has any preventative work for dry rot,wet rot, or damp ever been carried out to your property?  If you have answered yes, please give details:	No
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?  If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.  Guarantees are held by:	
14.	Guarantees	
a.	Are there any guarantees or warranties for any of the following?	
	(i) Electrical work	No
	(ii) Roofing	No
	(iii) Central heating	No
	(iv) National House Building Council (NHBC)	Yes

	(v) Damp course	No
	(vi) Any other work installations? (for example, cavity wall installation, underpinning, indemnity policy)	No
b.	If you have answered 'yes' or 'with title deeds', please give details of the installations to which the guarantee(s) relate(s):	e work or
C.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:	No
15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in thelast 10 years?	No
	If you have answered yes, please give details:	
16.	Notices that affect your property	
	In the past three years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	No
b.	that affects your property in some other way?	No
C.	that requires you to do any maintenance, repairs or improvements to your property?	No
	If you have answered yes to any of a-c above, please give the notices to yo or estate agent, including any notices which arrive at any time before the d of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief

Name(s): Clare Lyall

Date: 14/04/2024

### Residential

Home Report

Mortgage & Re-Mortgage Valuation Home & Flat Buyer Report

Energy Performance Certificate (EPC)

Private Sale Valuation

Inheritance Tax Valuation

Capital Gains Tax Valuation

Separation Valuation

**Driveby Valuation** 

Desktop Valuation

New Build, Development & Plot Valuation

Extension & Alteration Valuation

Portfolio Valuation

**Rental Valuation** 

**Expert Witness Report** 

Council Tax Appeal

Bespoke Condition Report

### Commercial

Commercial Valuation

Commercial Agency

Acquisitions & Disposals

Commercial Lease Advisory

Rent Reviews

Asset Management

Project Consultancy

**Development Appraisals** 

**Commercial Property Auctions** 

Property Management

**Professional Services** 

Licensed Trade / Leisure

### Property & Construction

Quantity Surveying

**Building Surveying** 

Project Management

Dispute Resolution Support Services

Principal Designer

Clerk of Works

Commercial EPC

Fire Engineering

Health & Safety Management

Employer's Agent

**Energy Department** 

Housing Services

**Development Monitoring** 

**Mediation Services** 

**Aberdeen**▲ ▲ 01224 202800

△ 01292 267987

Coatbridge △ 01236 436561

Cumbernauld △ 01236 780000

Dalkeith △ 0131 663 2780

Dumbarton △ 01389 731682

**Dumfries**▲ ▲ 01387 264333

#### Dundee

△ 01382 200454 ▲ 01382 220699

Dunfermline

▲ 01383 731841

East Kilbride △ 01355 248535

#### Edinburgh

△ 0131 2251234 ▲ 0131 557 9300

#### Elgin ▲ 01343 553939

Falkirk △ 01324 635 999

Fraserburgh △ 01346 517456

Galashiels

#### △ 01896 750150

Glasgow △ ▲ 0141 331 2807

#### Glasgow South △ 0141 649 8020

Glasgow West End △ 0141 353 2080

#### Greenock

△ 01475 730717

#### Hamilton △ 01698 897548

Inverness

△ ▲ 01463 712239

#### Kilmarnock

△ 01563 520318

Kirkcaldy △ 01592 205442

#### **Livingston**△ 01506 416777

Montrose △ 01674 676768

#### Motherwell △ 01698 252229

Musselburgh

△ 0131 653 3456

Oban △ 01631 707 800

Paisley
△ 0141 889 8334

Perth

△ 01738 638188 ▲ 01738 631631

#### Peterhead ▲ 01779 470766

St Andrews

△ 01334 477773

▲ 01334 476469

#### Saltcoats △ 01294 464228

Stirling

#### △ 01786 450438 ▲ 01786 474476







www.shepherd.co.uk www.hardies.co.uk