

10 PEFFER'S PLACE FORFAR DD8 3BB



# **Energy Performance Certificate**



# **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

#### 10 PEFFER'S PLACE, FORFAR, DD8 3BB

Dwelling type: Ground-floor flat
Date of assessment: 05 February 2024
Date of certificate: 05 February 2024

Total floor area: 72 m<sup>2</sup>

Primary Energy Indicator: 271 kWh/m²/year

**Reference number:** 0140-2395-8120-2604-2101 **Type of assessment:** RdSAP, existing dwelling

**Approved Organisation:** ECMK

**Main heating and fuel:** Boiler and radiators, mains


gas

#### You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£4,428	See your recommendations
Over 3 years you could save*	£1,506	report for more information

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (67)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (66)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Floor insulation (suspended floor)	£800 - £1,200	£651.00
2 Condensing boiler	£2,200 - £3,000	£852.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, filled cavity	***	<b>★★★☆☆</b>
Roof	(another dwelling above)	_	_
Floor	Suspended, no insulation (assumed)	_	_
Windows	Fully double glazed	***	<b>★★★☆☆</b>
Main heating	Boiler and radiators, mains gas	****	★★★★☆
Main heating controls	Programmer, TRVs and bypass	***	<b>★★★☆☆</b>
Secondary heating	Portable electric heaters (assumed)	_	_
Hot water	From main system	****	<b>★★★★</b> ☆
Lighting	Low energy lighting in all fixed outlets	****	****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 48 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.4 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.1 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

L-CE vv94.0.1.1 (SAP 9.94) Page 1 of 5

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£3,498 over 3 years	£2,073 over 3 years	
Hot water	£621 over 3 years	£540 over 3 years	You could
Lighting	£309 over 3 years	£309 over 3 years	save £1,506
Totals	£4,428	£2,922	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.


Da	sammandad massuras	Indiantive and	Typical saving	Rating after improvement		
Re	commended measures	Indicative cost	per year	Energy	Environment	
1	Floor insulation (suspended floor)	£800 - £1,200	£217	C 71	C 71	
2	Replace boiler with new condensing boiler	£2,200 - £3,000	£284	C 77	C 77	

#### **Alternative measures**

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Air or ground source heat pump
- Micro CHP

### Choosing the right improvement package





#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

#### 2 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	8,071	N/A	N/A	N/A
Water heating (kWh per year)	2,021			

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by ECMK (www.ecmk.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Steven Page
Assessor membership number: ECMK304051

Company name/trading name: Walker Fraser Steele
Address: 27 Waterloo Street

Glasgow G2 6BZ

Phone number: 07776655692

Email address: steven.page@esurv.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



# Scottish Single Survey



# survey report on:

Property address	10 Peffer's Place FORFAR Angus DD8 3BB
Customer	Aberdein, Considine & Company
Customer address	
Prepared by	Walker Fraser Steele
Date of inspection	5th February 2024

Walker Fraser Steele Chartered Surveyors

#### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report <sup>2</sup> will be from information contained in the Report and the generic Mortgage Valuation Report.

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

#### **WARNING:**

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	Subjects comprise a purpose-built, self contained former local authority ground floor flat forming part of a semi detached two storey block.
Accommodation	Ground Floor: Entrance Hall, Hallway, Lounge with Kitchen off, 3 Bedrooms and Bathroom with WC.
Gross internal floor area (m²)	72m2 approx.
Neighbourhood and location	The property is located within a mixed mainly residential location where local amenities are available.
Age	The property is understood to have been built in or around 1950.
Weather	At the time of our inspection it was mainly dry with intermittent light showers.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	Chimneys appear to be of masonry construction, surmounted by pots with flashings adjacent were visible.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	The roof is of pitched construction overlaid in slate, incorporating tiled ridge and hips.

Rainwater fittings  Visually inspected with the aid of binoculars where appropriate.  Rainwater fittings are of cast iron construction.  Visually inspected with the aid of binoculars where appropriate.  Foundations and concealed parts were not exposed or inspected.  The main walls appear to be of cavity masonry construction externally rendered.
Main walls  Visually inspected with the aid of binoculars where appropriate.  Foundations and concealed parts were not exposed or inspected.  The main walls appear to be of cavity masonry construction
appropriate.  Foundations and concealed parts were not exposed or inspected.  The main walls appear to be of cavity masonry construction
inspected.  The main walls appear to be of cavity masonry construction
Windows, external doors and joinery  Internal and external doors were opened and closed where keys were available.
Random windows were opened and closed where possible.
Doors and windows were not forced open.
Windows throughout are of uPVC double glazed design. Access to the property is via a uPVC and glazed rear entrance door and a uPVC side entrance panelled door.
Fortunal languages   Visually in the languages
External decorations Visually inspected.
External timbers have been painted orstained.
Conservatories / porches None
Communal areas None
Garages and permanent outbuildings None
Outside areas and boundaries Visually inspected.
Garden grounds are mainly laid to lawn. Boundaries comprise stone masonry walling, timber fencing and blockwork where seen. Rights of access should be confirmed as well as the extent of garden grounds.
Ceilings Visually inspected from floor level.
Ceilings appear to be of lath and plaster and plasterboard construction with heavy lined paper, plastered, textured and painted finishes.

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The property has solid masonry and plaster on the hard internal walls.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	The floors are of concrete and suspended timber construction.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Kitchen fitments comprise base and wall mounted fittings.
	Internal doors are of timber panel design.
	Joinery comprises skirting boards.
Chimney breasts and fireplaces	Visually inspected.
Chimney breasts and fireplaces	Visually inspected.
Chimney breasts and fireplaces	No testing of the flues or fittings was carried out.
Chimney breasts and fireplaces	
Chimney breasts and fireplaces  Internal decorations	No testing of the flues or fittings was carried out.
	No testing of the flues or fittings was carried out.  Chimney breasts have been boarded over in the past.
	No testing of the flues or fittings was carried out.  Chimney breasts have been boarded over in the past.  Visually inspected.
Internal decorations	No testing of the flues or fittings was carried out.  Chimney breasts have been boarded over in the past.  Visually inspected.  The property is in reasonable decorative order
Internal decorations	No testing of the flues or fittings was carried out.  Chimney breasts have been boarded over in the past.  Visually inspected.  The property is in reasonable decorative order

#### Gas

Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.

Mains supply of gas serving the subjects. The system was not in operation and was not tested.

#### Water, plumbing, bathroom fittings

Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.

No tests whatsoever were carried out to the system or appliances.

Mains supply of water and plumbing where seen of PVC and copper design.

Sanitary fittings comprise a three piece bathroom suite with WC.

The system was not in operation and was not tested.

#### Heating and hot water

Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.

No tests whatsoever were carried out to the system or appliances.

Full gas fired central heating system via the Worcester wall mounted combination boiler contained within the kitchen.

Domestic hot water is assumed to be provided directly from the heating system.

The system was not in operation and was not tested.

#### Drainage

Drainage covers etc. were not lifted.

Neither drains nor drainage systems were tested.

All foul and surface water drainage is assumed to be connected to the main public sewer. The system was not tested.

#### Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

Visually inspected. No test whatsoever or carried out to any system or appliances. There is now a requirement in place for compliant, interlinked fire, smoke, and heat detectors in residential properties. The new fire smoke and alarm standards came into force in Scotland in February 2022, requiring smoke alarms to be installed in the room, most frequently used for living purposes and in every circulation space on each floor. Heat alarms also required to be installed in each kitchen. The alarm needs to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance, such as

a boiler, open fire or wood burner etc. A carbon monoxide detector s also required. The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, linked and/or fully compliant with the fire and smoke alarm standard that was introduced in 2022. We have for the purposes of the report, assumed the system is fully compliant, if not, then the appropriate compliance system will required to be installed for sale. This of course should be confirmed by your legal advisor.

#### Any additional limits to inspection

#### For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property had fitted floor coverings, therefore no detailed inspection was possible of the floors and accordingly, no comment can be made on their condition. No access was available beneath sanitary or kitchen fittings. Windows and external doors were not all fully opened or tested. No access was available to any subfloor areas. We were not able to fully inspect all areas of boundary walls/fences due to garden vegetation. No inspection has been possible to flooring timbers beneath sanitary fittings or kitchen appliances and timbers are assumed to be in a satisfactory condition. All services have been disconnected and were not checked or tested. Access to the attic roof void is out with the subject flat and according no access was afforded and no comment can be made as to its condition.

### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1 Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 17) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- 0) Verge boards /skews
- (21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- 25) Window pointing
- 26) Window sills
- (27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- Water tank
- 10) Hot water tank

#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	1
Notes	No evidence of significant structural movement was noted.

Dampness, rot and infestation	
Repair category	2
Notes	Staining, decay to wall linings and above average damp readings were obtained to localised sections of lower wall lining at ground floor level. A full and thorough inspection of the entire property should be carried out by a reputable timber specialist prior to purchase.

Chimney stacks	
Repair category	2
Notes	Weathered and defective chimney masonry is visible and repairs are required.

Roofing including roof space	
Repair category	2
Notes	A number of loose or broken roof slates and components were visible. Roof coverings are of an age and style where are degree of regular ongoing maintenance should be anticipated. To fully ascertain the condition of the roof coverings further advice should be obtained from a firm of roofing contractors prior to purchase.

Rainwater fittings	
Repair category	2
Notes	Staining was noted to gutters and adjacent walls suggestion previous leakage. Inspect and repair as necessary. Where previous leakage has occurred, a precautionary check of the surrounding area is advised by timber specialist.

Main walls	
Repair category	2
Notes	Sections of render to the property are cracked and bossed. Repairs are required. Cracked and bossed sills were noted and repairs are required. Further advice should be ascertained from a firm of reputable building contractors.

Windows, external doors and joinery	
Repair category	2
Notes	The kitchen window is ill fitting and repairs or replacment is required. Some items of wear and tear including stiff and ill fitting units and mechanisms were also noted elsewhere. Double glazed units are defective having failed and allowed condensation to form between the panes. Repairs, including the replacement of defective units, will be required.

External decoration	s
Repair category	1
Notes	Paint finished and decorated external surfaces willrequire redecoration on a regular basis

Conservatories/porches	
Repair category	-
Notes	Not Applicable

Communal areas	
Repair category	-
Notes	Not Applicable

Garages and permanent outbuildings	
Repair category	-
Notes	Not Applicable

Outside areas and boundaries	
Repair category	1
Notes	Boundary walls/fences are damaged, weathered and leaning and repairs are required.

Ceilings	
Repair category	1
Notes	Textured coatings were noted to ceiling areas. On rare occasions, These materials can have an asbestos content. We have not tested these materials nor carried out on asbestos survey however, until the material is professionally tested, the ceilings should be left undisturbed and the material handled by a competent contractor only.

Internal walls	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Floors including sub-floors	
Repair category	2
Notes	Due to fitted carpets and floor coverings no detailed inspection of floors was possible and accordingly no comment can be made on the air condition. There was evidence of spillage adjacent to the shower/bath flooring and surfaces within the bathroom, this area should be checked for damp and rot as a precaution and any repairs implemented as necessary.

Internal joinery and kitchen fittings	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Chimney breasts and fireplaces	
Repair category	1
Notes	Fireplaces have been removed or blocked without adequate ventilation installed. Ventilators should be fitted to prevent the build up of dampness within the chimney flue.

Internal decorations	
Repair category	1
Notes	Upgrade to meet purchasers requirements.

Cellars	
Repair category	-
Notes	Not Applicable

Electricity	
Repair category	3
Notes	All electrical services have been disconnected. These should be reinstated under professional supervision with any associated repairs or upgrading carried out in full by registered electrical contractor.

Gas	
Repair category	3
Notes	All gas services have been disconnected. These should be reinstated under professional supervision with any associated repairs or upgrading carried out in full by a gas safe registered contractor.

Water, plumbing and bathroom fittings	
Repair category	2
Notes	As mentioned staining was noted to flooring/surfaces adjacent to the bath/shower. No access was available beneath sanitary fittings and a precautionary check for damp/rot is recommended.

Heating and hot water			
Repair category	3		
Notes	The heating system has been disconnected/drained down. This should be reinstated under professional supervision with any required repairs or upgrading carried out by a reputable contractor.		

Drainage	
Repair category	1
Notes	All foul and surface water drainage is assumed to be connected to the main public sewer. The system was not tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	2
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	2
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	3
Gas	3
Water, plumbing and bathroom fittings	2
Heating and hot water	3
Drainage	1

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground Floor		
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No		
3. Is there a lift to the main entrance door of the property?	Yes No X		
4. Are all door openings greater than 750mm?	Yes No X		
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No		
6. Is there a toilet on the same level as a bedroom?	Yes X No		
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No		
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No		

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

Your legal adviser should confirm if there are any current or future repairs which are planned and explain your liability as a lessee for the repair and maintenance of the common areas. Records of any fire safety risk assessment and electrical testing of the common parts should also be obtained and reviewed. Your legal adviser should also discuss with you any possible restrictions on the use of the property.

Your legal adviser should make further enquiries and advise you on what rights you have over neighbouring property to maintain the external fabric. Your legal adviser should make further enquiries and advise you on If there are any easements or rights enjoyed by neighbours over the property such as the 'right to light' or the 'right to support' or the 'right for drainage to pass beneath the property' etc.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Some materials within the property may have an asbestos content including textured ceilings and ceiling boards. We have not tested these materials and are not acting as Licensed Asbestos Inspectors. These materials should be left undisturbed until advice is obtained from a Licensed Specialist.

The subjects form part of a block of flats and it has been assumed that maintenance/repair costs of the common parts of the building will be shared on an equitable basis with adjoining proprietors. It is therefore assumed that the cost of common repairs detailed within the report will be apportioned accordingly although exact liability should be confirmed.

Confirm rights of way and extent of garden grounds.

The property may have been repossessed by a heritable creditor. Normal warranties may not be available including utilities/services which may require to be professionally re-commissioned.

#### Estimated reinstatement cost for insurance purposes

The estimated reinstatement cost for insurance purposes is £160,000 (ONE HUNDRED AND SIXTY THOUSAND POUNDS STERLING). This figure is an opinion of an appropriate sum for which the property should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings, finishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised. The figure should be reviewed annually and in light of any future alterations or additions.

#### Valuation and market comments

The market value of the property as described in this report is £88,000 (EIGHTY-EIGHT THOUSAND POUNDS STERLING).

This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights.

Signed	Security Print Code [578519 = 7905 ] Electronically signed				
Report author	Connor Stephen				
Company name	Walker Fraser Steele				
Address	1st Floor, Suite 1/3, 27 Waterloo Street, Glasgow, G2 6BZ				
Date of report	5th February 2024				

# Mortgage Valuation Report

# Walker Fraser Steele Chartered Surveyors

Property Address					
Address Seller's Name Date of Inspection	10 Peffer's Place, FORFAR, Angus, DD8 3BB Aberdein, Considine & Company 5th February 2024				
Property Details					
Property Type	House Bungalow Purpose built maisonette Converted maisonette  X Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)				
Property Style	□ Detached       □ Semi detached       □ Mid terrace       □ End terrace         □ Back to back       □ High rise block       X Low rise block       □ Other (specify in General Remarks)				
Does the surveyor be e.g. local authority, m	lieve that the property was built for the public sector, X Yes No ilitary, police?				
Flats/Maisonettes only Floor(s) on which located Ground No. of floors in block 2 Lift provided? Yes X No No. of units in block 4					
Tenure					
X Absolute Ownership	Leasehold Ground rent £ Unexpired years				
Accommodation					
Number of Rooms	1 Living room(s)     3 Bedroom(s)     1 Kitchen(s)       1 Bathroom(s)     1 WC(s)     0 Other (Specify in General remarks)				
Gross Floor Area (excluding garages and outbuildings) $\boxed{72}$ m² (Internal) $\boxed{82}$ m² (External) Residential Element (greater than 40%) $\boxed{X}$ Yes $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $					
Garage / Parking / 0	Outbuildings				
Single garage Available on site?	□ Double garage       □ Parking space         □ Yes       ▼ No             □ No garage / garage space / parking space				
Permanent outbuilding	gs:				

# Mortgage Valuation Report

Construction								
Walls	X Brick	Stone	Concre	ete Timber f	rame	Other (specify in General Remark		
Roof	Tile	X Slate	Aspha	t Felt	Other (specify in General Remarks)			
Special Risks								
Has the property	suffered struc	tural movem	ent?				Yes	X No
If Yes, is this rece	nt or progres	sive?					Yes	No
Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in the immediate vicinity?						X No		
If Yes to any of th	e above, prov	vide details ir	General Rem	arks.				
Service Connec	ctions							
Based on visual ir of the supply in G			vices appear to	be non-mains,	please co	mment o	n the type a	nd location
Drainage	X Mains	Private	None	W	ater X	Mains	Private	None
Electricity	X Mains	Private	None	Ga	as X	Mains	Private	None
Central Heating	X Yes	Partial	None					
Brief description of	of Central Hea	ating:						
Full gas to radiat	tors							
Site								
Apparent legal iss	sues to be ver	rified by the o	conveyancer.	Please provide	a brief des	cription in	n General R	emarks.
Rights of way	X Shared dri	ves / access	Garage or o	ther amenities on s	eparate site	Share	ed service conn	ections
Ill-defined boundar	ries	Agricu	Itural land include	d with property		Other	(specify in Ger	eral Remarks)
Location								
Residential suburb	X Re	sidential within t	own / city	Mixed residential / d	commercial	Mainly	y commercial	
Commuter village	Re	mote village		Isolated rural prope	rty	Other	(specify in Ger	neral Remarks)
Planning Issues	s							
Has the property been extended / converted / altered?  Yes X No								
If Yes provide details in General Remarks.								
Roads								
X Made up road	Unmade roa	ıd Partly	y completed new	oad Pede	strian access	only	Adopted	Unadopted

#### Mortgage Valuation Report

General Remarks
Subjects comprise a purpose-built, self contained former local authority ground floor flat forming part of a semi detached two storey block. The property is located within a mixed mainly residential location where local amenities are available.
The property may have been repossessed by a heritable creditor. Normal warranties may not be available including utilities/services which may require to be professionally re-commissioned.
Staining, decay to wall linings and above average damp readings were obtained to localised sections of lower wall lining at ground floor level. A full and thorough inspection of the entire property should be carried out by a reputable timber specialist prior to purchase.
The general condition of the property appears consistent with its age and type of construction however elements of the property are aging likely requiring attention.
Essential Repairs
None apparent for mortgage purposes
Estimated cost of essential repairs £ Retention recommended? YesX No Amount £

#### Mortgage Valuation Report

Comment on Mortgagea	bility	
The property forms suitable mortgage provider.	e security for mortgage purposes subject to the specific lending criteria o	f any
Valuations		
Market value in present con Market value on completion Insurance reinstatement va (to include the cost of total in Is a reinspection necessary	of essential repairs lue ebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 88,000 £ - £ 160,000
Buy To Let Cases		
month Short Assured Tenai	•	£
Is the property in an area w	here there is a steady demand for rented accommodation of this type?	YesNo
Declaration		
Signed Surveyor's name	Security Print Code [578519 = 7905 ] Electronically signed by:- Connor Stephen	
Professional qualifications	MRICS	
Company name	Walker Fraser Steele	
Address	1st Floor, Suite 1/3, 27 Waterloo Street, Glasgow, G2 6BZ	
Telephone	0141 221 0442	
Fax	0141 258 5976	

Report date

5th February 2024

#### Sellers Property Questionnaire



Property address	10 PEFFER'S PLACE, FORFAR, DD8 3BB
Seller(s)	Aberdein Considine
Completion date of property questionnaire	29/01/2024

#### **Note for sellers**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

#### Information to be given to prospective buyer(s)

1.	Length of ownership
	How long have you owned the property? Cannot answer*
2.	Council tax
	Which Council Tax band is your property in? (Please circle)
	A B C D E F G H Cannot answer*
3.	Parking
	What are the arrangements for parking at your property?
	(Please tick all that apply)
	• Garage
	Allocated parking space
	• Driveway
	Shared parking
	On street
	Resident permit
	Metered parking
	Other (please specify):
	Cannot answer*
4.	Conservation area
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?  Yes / No / Don't know Cannot answer*

5.	Listed buildings	
	Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?	Yes / No Cannot answer*
6.	Alterations/additions/extensions	
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?  If you have answered yes, please describe below the changes which you have made:	Yes / No Cannot answer*
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?  If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.  If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	Yes / Ne
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?  If you have answered yes, please answer the three questions below:	Yes / No Cannot answer*
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes / No
	(ii) Did this work involve any changes to the window or door openings?	Yes / No
	(iii) Please describe the changes made to the windows, doors or patio doors (vidates when the work was completed):	vith approximate
	Please give any guarantees which you received for this work to your solicitor or	estate agent.

7.	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	Yes / No / Partial Cannot answer*
	If you have answered yes / partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	If you have answered yes, please answer the three questions below:	
b.	When was your central heating system or partial central heating system installed?	
C.	Do you have a maintenance contract for the central heating system?	Yes / No
	If you have answered yes, please give details of the company with which you have a maintenance contract:	
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes / No Cannot answer*
9.	Issues that may have affected your property	
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes / No Cannot answer*
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	<del>Yes</del> / <del>Ne</del>
b.	Are you aware of the existence of asbestos in your property?	Yes / No Cannot answer*
	If you have answered yes, please give details:	Carriot answer

10. a.	Services  Please tick which services are	connected to yo	ur property and give detail	s of the
a.	supplier:	connected to yo	ar property and give detail	3 Of the
	Services	Connected	Supplier	
	Gas / liquid petroleum gas	Cannot answer*		
	Water mains / private water supply	Cannot answer*		
	Electricity	Cannot answer*		
	Mains drainage	Cannot answer*		
	Telephone	Cannot answer*		
	Cable TV / satellite	Cannot answer*		
	Broadband	Cannot answer*		
b.	Is there a septic tank system at you have answered yes, please		estions below:	Yes / No Cannot answer*
C.	(i) Do you have appropriate conse	nts for the discha	rge from your septic tank?	Yes / No / Den't knew
d.	(ii) Do you have a maintenance co	ntract for your se	otic tank?	Yes / No
	If you have answered yes, please have a maintenance contract:	e give details of the	ne company with which you	

11.	Responsibilities for Shared or Common Areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Yos / No / Don't Know Cannot answer*
	If you have answered yes, please give details:	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes / No / Not applicable Cannot answer*
	If you have answered yes, please give details:	
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes / No Cannot answer*
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?	Yes / No Cannot answer*
	If you have answered yes, please give details:	
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Yes / No Cannot answer*
	If you have answered yes, please give details:	
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	Yes / No Cannot answer*
	If you have answered yes, please give details:	
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?	Yes / No Cannot answer*
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	

b.	Is there a common buildings insurance policy?	Yes / No / Den't Knew Cannot answer*
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	<del>Yes</del> / <del>Ne</del> / <del>Den't Knew</del>
C.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes / No Cannot answer*
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:	
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Yes / No Cannot answer*
	If you have answered yes, please give details:	
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	Yes / No
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	
	Guarantees are held by:	

14.	Guarantees						
a.	Are there any guarantees or warranties for an	y of the	following	:			
(i)	Electrical work	No	Yos	Don't know	With title doods	Lost	Cannot Answer*
(ii)	Roofing	Ne	Yes	Don't know	With title doods	Lost	Cannot Answer*
(iii)	Central heating	No	Yos	Don't know	With title deeds	Lost	Cannot Answer*
(iv)	NHBC	No	¥os	Don't know	With title doods	Lost	Cannot Answer*
(v)	Damp course	Ne	Yes	Don't know	With title doods	Lost	Cannot Answer*
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No	Yos	Don't know	With title doods	Lost	Cannot Answer*
b.	If you have answered 'yes' or 'with title deed or installations to which the guarantee(s) rela	ls', pleas ite(s):	se give de	etails of t	he work		
C.	Are there any outstanding claims under any of the guarantees listed above?  If you have answered yes, please give details:				¥ee	-/ <del>No</del>	
15.	Boundaries						
	So far as you are aware, has any boundary of your property been moved in the last 10 years?  If you have answered yes, please give details:				Don'	/ Ne / t know answer*	

16.	Notices that affect your property	
	In the past 3 years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Yes / No / Don't know Cannot answer*
b.	that affects your property in some other way?	Yos / No / Don't know Cannot answer*
C.	that requires you to do any maintenance, repairs or improvements to your property?	Yos / No / Don't know Cannot answer*
	If you have answered yes to any of a-c above, please give the notices to your sagent, including any notices which arrive at any time before the date of entry of your property.	olicitor or estate the purchaser of

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):		
Date:		

<sup>\*</sup> This report has been completed on behalf of the lender in respect to a repossessed property and therefore some information is not available.

