| Energy performance certificate (EPC) | | |
|---|-------------------|--|
| 58 Fern Towers Harestone Hill CATERHAM CR3 6SL | Energy rating | Valid until: 20 October 2033 Certificate number: 7016-6297-5002-0120-6292 |
| Property type | Ground-floor flat | |
| Total floor area | 79 square metres | |

Rules on letting this property

Properties can be let if they have an energy rating from A to E.

You can read <u>guidance for landlords on the regulations and exemptions</u> (<u>https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance</u>).

Energy rating and score

This property's current energy rating is C. It has the potential to be C.

<u>See how to improve this property's energy</u> <u>efficiency</u>.

| Score | Energy rating | Current | Potential |
|-------|---------------|---------|-----------|
| 92+ | Α | | |
| 81-91 | В | | |
| 69-80 | С | 69 C | 76 C |
| 55-68 | D | | |
| 39-54 | E | | |
| 21-38 | F | | |
| 1-20 | | G | |

The graph shows this property's current and potential energy rating.

Properties get a rating from A (best) to G (worst) and a score. The better the rating and score, the lower your energy bills are likely to be.

For properties in England and Wales:

the average energy rating is D the average energy score is 60

Breakdown of property's energy performance

Features in this property

Features get a rating from very good to very poor, based on how energy efficient they are. Ratings are not based on how well features work or their condition.

Assumed ratings are based on the property's age and type. They are used for features the assessor could not inspect.

| Feature | Description | Rating |
|----------------------|--|-----------|
| Wall | Cavity wall, as built, no insulation (assumed) | Poor |
| Wall | Solid brick, as built, no insulation (assumed) | Poor |
| Window | Fully double glazed | Average |
| Main heating | Boiler and radiators, mains gas | Good |
| Main heating control | TRVs and bypass | Average |
| Hot water | From main system | Good |
| Lighting | Low energy lighting in all fixed outlets | Very good |
| Roof | (another dwelling above) | N/A |
| Floor | Solid, no insulation (assumed) | N/A |
| Secondary heating | None | N/A |

Primary energy use

The primary energy use for this property per year is 223 kilowatt hours per square metre (kWh/m2).

Additional information

Additional information about this property:

• Cavity fill is recommended

How this affects your energy bills

An average household would need to spend **£685 per year on heating, hot water and lighting** in this property. These costs usually make up the majority of your energy bills.

You could **save £166 per year** if you complete the suggested steps for improving this property's energy rating.

This is **based on average costs in 2023** when this EPC was created. People living at the property may use different amounts of energy for heating, hot water and lighting.

Heating this property

Estimated energy needed in this property is:

- 9,123 kWh per year for heating
- 1,903 kWh per year for hot water

| Impact on the environment | | This property produces | 3.1 tonnes of CO2 |
|--|-----------------|--|-------------------|
| This property's current env rating is D. It has the poten | • | This property's potential production | 2.1 tonnes of CO2 |
| Properties get a rating from A (best) to G (worst) on how much carbon dioxide (CO2) they produce each year. CO2 harms the environment. | | You could improve this property's CO2 emissions by making the suggested changes. This will help to protect the environment. | |
| Carbon emissions | | These ratings are based on assumptions about average occupancy and energy use. People living at the property may use different | |
| An average household produces | 6 tonnes of CO2 | amounts of energy. | |

Changes you could make

| Step | Typical installation cost | Typical yearly saving |
|---|---------------------------|-----------------------|
| 1. Cavity wall insulation | £500 - £1,500 | £79 |
| 2. Internal or external wall insulation | £4,000 - £14,000 | £24 |
| 3. Floor insulation (solid floor) | £4,000 - £6,000 | £63 |

Help paying for energy improvements

You might be able to get a grant from the <u>Boiler Upgrade Scheme (https://www.gov.uk/apply-boiler-upgrade-scheme)</u>. This will help you buy a more efficient, low carbon heating system for this property.

More ways to save energy

Find ways to save energy in your home by visiting www.gov.uk/improve-energy-efficiency.

Who to contact about this certificate

Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

| Assessor's name | Ross Yellowlees |
|-----------------|------------------------------|
| Telephone | 07944625061 |
| Email | rossyellowlees@hotmail.co.uk |

Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

| Accreditation scheme | Quidos Limited |
|----------------------|-------------------|
| Assessor's ID | QUID206987 |
| Telephone | 01225 667 570 |
| Email | info@quidos.co.uk |

About this assessment

| Assessor's declaration | No related party |
|------------------------|------------------|
| Date of assessment | 20 October 2023 |
| Date of certificate | 21 October 2023 |
| Type of assessment | RdSAP |